


Wellness Index Tracking system (WITs) - Smart Watch

WITs Overview



Specifications


Processor	ARM4
Display	TFT LCD
Touch Screen	Support
Sensors/activity tracker	Accelerometer Gyro Electronic Compass Heart Rate Oximeter Barometer Motor Buzzer Walking / Running Steps Calories consumption
GPS	Support
Physical	5 Aluminum Buttons Ceramic Watch Ring Plastic Watch Case Silicon Strap Aluminum Bottom Cover
Language	Chinese / English
Battery capacity	320mAh
Battery voltage	4.2V
Charging	USB Type C
Working temperature and humidity	0°C to 60°C / 10%-90%

*Photo is for reference only.


Feature Highlights

Pre-scheduled measurement


Pre-scheduled measurement



Blood oxygen level



Blood pressure level



Time gap setting

- Set time gap on watch interface
- **Remote time gap setting** through server program or application



10 mins 30 mins

1 hours 2 hours 3 hours

4 hours 6 hours


Re-measure after 10 mins if no data was measured on the first measurement
Displays as 0 if no data was measured on the re-measurement

Remote measurement




Remote measurement through server program or application

Displays as 0 if no data was measured



Blood oxygen level



Blood pressure level

SOS function



Press any button or cover watch surface
for 10 secs
to activate the **SOS alert**



Turn off SOS alert on **watch interface**
or **remote turn off** through server
program or application

Real time broadcast data



Heart rate



Running steps



Blood pressure



Blood oxygen



Battery



Walking steps



SOS



Calories consumption

Automatically broadcast data to server when the watch is connected